


Object dimensions can be definitively made using three sensors as above. On an assembly line, for instance, it may be possible to measure dimension as the object moves past a static sensor.



Object Dimensions